

refers to the Quality Level	Dimensions	are in inche	COAST/ACM						
(C, B, E, or S), see Quality Assurance	tolerances a Fractions	re: Decimals .xx = ±0.03	03 +1/2°	TITLE Power Transformer					
Provisions above.	±1/64	.XX = ±0.03 .XXX=±0.010		FSCM		DWG. N			REV.
	DRAWN BY		DATE	22558		33077X			
DO NOT SCALE DRAWING	Jim Allen		11/5/03	SCALE: none	e MA	AX. WT.:	54 grams	SHEET	1 OF 1