

refers to the Quality Level	Dimensions are in inches, and			COAST/ACM						
-	tolerances are:			TITLE						
(C, B, E or S), see Quality	Fractions	ractions Decimals And								
Assurance Provisions	±1/64 .XX = ±0.03 .XXX=±0.010			Inductor						
above.				FSCM			DWG. N	10		REV.
	DRAWN BY		DATE	22558		8	31732X			
DO NOT SCALE DRAWING	Jim Allen		05/12/03	SCALE	E: none MAX.		X. WT.:	25 grams	SHEET	1 OF 1